

Appendix A

Squaw Creek Watershed Photographs – 1999



Figure A-1. Ski Area Grading and Road Development



Figure A-2. Erosion From Dirt Roads and Drainage Crossings



Figure A-3. Erosion From Dirt Roads and Drainage Crossings



Figure A-4. Erosion From Road Drainage




Figure A-5. Erosion From Graded Ski Runs



Figure A-6. Erosion From Graded Ski Runs



Figure A-7. Erosion Below Culvert Outlets



Figure A-8. Erosion Below Culvert Outlets